

STOP!

be sure...be ParaSure

Type 4 Multi-Parameter Indicators

Unprocessed indicator Large square is pale pink





Successfully processed indicator

All lines shows evidence of black.

PASS

Items in tray/pack can be safely used



Unsuccessfully processed indicator

one or more lines shows evidence of pink.

FAIL

Do NOT use items in tray/pack



Unsuccessfully processed indicator

one or more lines shows evidence of pink.

FAIL

Do NOT use items in tray/pack



Unsuccessfully processed indicator

one or more lines shows evidence of pink.

FAIL

Do NOT use items in tray/pack

PS1110 Type 4 Multi-Parameter Indicators



Registered Address:

ParaSure Limited Units B10/11 Oakendene Estate Bolney Rd Cowfold West Sussex RH13 8AZ England





STOP!

be sure...be ParaSure

Type 4 Multi-Parameter Indicators

Unprocesed indicator Large square is pale pink





Successfully procesed indicator

Large square is as dark or darker than small square

PASS

Items in tray/pack can be safely used

BEFERING COLUMN COLUMN

Unsuccessfully procesed indicator

Large square shows evidence of pink

FAIL

Do NOT use items in tray/pack



Unsuccessfully procesed indicator

Large square shows evidence of pink

FAIL

Do NOT use items in tray/pack



Unsuccessfully procesed indicator

Large square shows evidence of pink

FAIL

Do NOT use items in tray/pack

PS1110 Type 4 Multi-Paramter Indicators



Registered Address:

ParaSure Limited Units B10/11 Oakendene Estate Bolney Rd Cowfold West Sussex RH13 8AZ England

